



STATE OF NEVADA
DEPARTMENT OF CONSERVATION AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL PROTECTION

CAPITOL COMPLEX
CARSON CITY, NEVADA 89710

December 13, 1978

TELEPHONE (702) 885-4670

Art Aten
Star Route, Antelope Valley
Battle Mountain, Nevada 89820

Dear Mr. Aten:

Enclosed is a copy of the latest "Pesticide Container Disposal Site Inspection Report" for the Antelope Valley site. As you can see from the inspection form, the site was in the same condition as it was in August. Judging from the site appearance, it appears as though the site has been abandoned. If the site has been abandoned then it may be necessary to close the site.

In order for the Division to make future decisions regarding the Antelope Valley site it is necessary to at least answer the following questions:

1. Has the Antelope Valley site been abandoned?
2. Is another site being utilized to dispose of pesticide containers?
3. Where are pesticide containers being disposed if they are not going to the site?
4. What are the ramifications of closing the site?
5. If locals want to keep the site open, who will be the responsible party for site operation?

It would be my pleasure to meet with you, Ken Carper or other interested individuals concerning this problem. At your convenience, could you please drop me a note regarding a possible meeting date so that we can discuss the above problems or any others? Thanks for your cooperation.

Sincerely,

Frank J. Luchetti
Hazardous Waste Management Specialist

kc

PESTICIDE CONTAINER DISPOSAL SITE
INSPECTION FORM

Site Name Antelope Valley Date 11/17/78
County San Diego Location Antelope Valley
Responsible Entity _____ Entity Representative none
Equipment on site None
Witnessed by Frank Luskett

METHOD OF OPERATION

Truck

ACCESSIBILITY (☒) Acceptable () Unacceptable

Are roads acceptable leading to site? Y
Litter cleaned? Y Maintained? Y Safe? Y
Remarks _____

WATER POLLUTION (☒) Acceptable () Unacceptable

Is site in apparent stream or runoff channel? N
Evidence of flooding or erosion in disposal area? N
Remarks _____

AIR POLLUTION (☒) Acceptable () Unacceptable

Is site burning? N Estimated date of last burning? NA
Does fire hazard appear to exist? N Any evidence of fires? N
Remarks _____

COVERING CONTROL () Acceptable (☒) Unacceptable

Estimated date of last covering None Per Cover
Is open face kept to a minimum? X Estimated size _____
Cover depth? NONE (24" required)
Remarks _____

PROTECTIVE FENCING () Acceptable (☒) Unacceptable

Area fenced Entire Area
Back breaker on each post? Y Fence height 8'
Fencing material 4x4x2x2 Mesh 5 Strand Barb
Earth berm around fence? N Earth berm height 24" None
Metal gate? Y Locked gate? Y
Warning signs indicating poisonous chemicals disposal area? N
Sign minimum spacing No Signs
Remarks _____

DRAIN SUMP

() Acceptable () Unacceptable

Within fenced area? None

_____ ft. wide _____ ft. long _____ ft. deep

Mode of operation _____

Remarks _____

OTHER FACILITIES

() Acceptable () Unacceptable

Building on site? X _____ 8 ft. wide _____ 8 ft. long

Safety equipment and clothing on site _____

Sanitary facilities? N Water supply? N Estimation of water supply N

Spill flushing facility? N Shower? N Hand faucet? N

Remarks _____

SALVAGE OPERATIONS N/A

() Acceptable () Unacceptable

List, if any _____

Remarks _____

Items needing immediate attention _____

Estimated date for followup inspection _____

Copy of report given/sent to _____

Inspected by CR Luthman

Y = Yes N. Obs. = None Observed

N = No or none Picture nos. _____